LOCAL NOTICE TO MARINERS

U.S. Department of Transportation

United States Coast Guard

WEEKLY SUPPLEMENT - MAY 1997

**FAX-ON-DEMAND - LOCAL NOTICE TO MARINERS AT (703) 313-5931 or 5932 ** ** Electronic Bulletin Board Service: (703) 313-5910 **

300 to 28.8 bps, 8 data bite, no parity 1 stop bit NIS watchstander, 24 hours a day at (703) 313-5900 ~ INTERNET ADDRESS ~ http://www.navcen uscg.mil OR ftp://ftp.navcen.uscg.mil

Commander (mon) Issued by:

> Seventeenth Coast Guard District P O Box 25517 Juneau, AK 99802-5517

Telephone: (907) 463-2262 (0800-1600) (907) 463-2004 (1600-0800)

Facsimile: (907) 463-2273

Questions comments or additional information on this Local Notice to Mariners or the Local Notice to Mariners mailing list (additions, deletions, corrections) should be directed to the address above.

For faster service, get the 17~ District Local Notice to Mariners via e -mail. To get on our electronic mailing list, send us an e -mail at: akcgnav@alaska.net

LIGHT LIST REFERENCE: COMDTPUB P16502.6 VOL. VI 1996 EDITION

BROADCAST NOTICE TO MARINERS

Navigation information previously promulgated by Broadcast Notice to Mariners 539/96 through 182/97 and still in effect is included in this notice.

USE OF THE LOCAL NOTICE TO MARINERS

The Weekly Supplemental editions contain new information available subsequent to the issue of the Monthly edition. To ensure having complete information concerning the waterways of the Seventeenth Coast Guard District, consult Monthly edition 19/97.

I SPECIAL NOTICES

KODIAK-DGPS-OFF-AIR

During the period of 1500Z 19 May 97 to 0300Z 22 May 97 there will be intermittent outages of the DGPS signal from Miller Field (Kodiak) DGPS site. No outage will exceed 2 hours.

KODIAK-LORANC-PROPOSED OFFAIR

This is a proposal to authorize Loran Station Kodiak (796%/9990-Z) off-air time from 1800Z to 2000Z on 19 Jun 1997. The alternate time will be from 1800Z to 2000Z on 25 Jun 1997. Objections will be considered until 1800Z on 13 Jun 1997. Users shall address inquiries to the North Pacific Coordinator of Chain Operations at (907) 487-5183. Current Loran C status is available 24 hours a day through an electronic bulletin board system (BBS) at (703) 3-53910, baud rate 300 to 28,800. Communications parameters are eight bit word, one stop bit, no parity. Internet address: http://hAnNw.navcen.uscg.mil

HOLKHAM BAY-TRACY ARM LIGHT

Tracy Arm Light (LLNR 23635) now displays a fixed White sector light along the centerline of the channel, on a bearing of 215 degrees true. The white sector is bordered by alternating Red and White sectors denoting the limits of the safe navigable channel. This establishes a reciprocal range from Holkham Bay Range (LLNR's 23625 and 23630). This Aid will display its lighted signal both Night and Day, until its seasonal decommissioning date of 30 September.

II DISCREPANCIES DISCREPANCIES CORRECTED

DISCREPANCIES:

LLNR N	AME OF AID	STATUS	CHART	BNM	LNM		
22429.5	Thorne Bay Channel Daybeacon "7"	Destroyed	17405	657/96	48/96		
23305.6	Keku Strait Daybeacon "9"	Destroyed	17372	161/97	18/97		
23305.8	Keku Strait Daybeacon "11"	Destroyed	17372	161/97	18/97		
24975	Crescent Harbor West Breakwater Light "3"	Leaning	17327	158/97	19/97		
DISCREPANCIES/PRIVATE AIDS:							

LLNR NAME OF AID	STATUS	CHART	BNM	LNM
26007 Seward Forest Dock Mooring Lights (2)	Extinguished	16682	539/96	39/96
27467 APL Dolphin Lights	Extinguished	16011	178/97	20/97
27467 APLShoal Lighted Buoys	Extinguished	16011	178/97	20/97

REPORT DEFECTS IN AIDS TO NAVIGATION TO THE NEAREST COAST GUARD UNIT

Date: 14 MAY 1997 NOTICE NUMBER 20

III <u>TEMPORARY CHANGES TEMPORARY CHANGES CORRECTE</u>D

	<u>IAME OF AID</u> ape St.Elias Bell Bu		<u>ATUS</u> B	<u>CHART</u> 16723	BNM 121/97	<u>LNM</u> 13/97	
	Anchor Point Light		W 6s 7M	16645	437/96	30/96	
V <u>CHAI</u>	RT CORRECTIONS	3					
16006		Alaska Bearing Sea Eastern Part Last LNN - Bering Sea - Eastern Part	1 45/9 6NAD 83	(NOS CL 9	26/96)		20/9
	Add::	depth, 7 fathoms		62°06'00.0	""N	167°46'46.0"W	
		depth, 7 1/2 fathoms		62°10'00.0	""N	167°42'00.0"W	
		depth, 8 fathoms		62°15'00.0	""N	167°37'30.0"W	
16490		Last LNM 22/95 NAD 83 lia Island - Nazan Bay and Amilia Pass		(NOS CL 9	26/96)		20/97
	Add:	Dashed line (label Sewer) from		52°12'25.4	"N	174°12'03.4"W	
	71001	to		52°12'31.0		174°11'49.5"W	
16566	8th Ed.08/03/96 Last LNM 04/97 NAD 83 20/97			(NOS H 10692 to 10695/10698)			
		nsula - Chignik and Kujulik Bays					
	Add:	Shoal, covers 2 ½ fathoms		56°35'57.9		157°42'34.4"W	
		Shoal covers 4 ½ fathoms		56°36'04.1	″N	157°42'42.0"W	
16662	20/97	_ast LNM 50/96 NAD 83		(CCGD1	7)		
	AK - Cook Inlet - I Change:	Kalgin Island to North Foreland Light to QR 22feet		60°40'20.0	"N	151°23'33.0"W	
17300		Last LNM 09/97 NAD 83 past - Stephens Passage to Cross Sound	including Lynn Canal	(NOS CL-5	9/97)		20/97
	Add:	rock, 3 fathoms		58°18'34.4		134°41"20.857"W	
		rock, awash shoal, 9 fathoms		58°18'22.6 58°19'03.5		134°40"55.912"W	
		rock 1 % fathoms		58°18'28.9		134°41"26.147"W 134°41.22.621W	
		rock 4 fathoms		58°16'52.7		134°45"27.897"W	
		rock 2 fathoms		58°16'43.4		134°44"18.427"W	
		rock 3 ¼ fathoms		58°17'19.5		134°41"00.080"W	
		rock 5 ¼ fathoms rock 3 ¼ fathoms		58°15'52.8 58°17'07.3		134°42"54.807"W 134°40"50.229"W	
		shoal covers 1 fathom		58°14'18.2		134°43"23.658"W	
		rock awash 1/2 fathom		58°15'38.2		134°42"22.196"W	
		rock covers 2 fathoms		58°12'09.1		134°38"40.737"W	
		shoal covers 2 ¼ fathoms shoal covers 6½ fathoms		58°15'08.8 58°15'22.2		134°41"55.630"W 134°38"53.370"W	
		Siloai covers 0/2 fatiloffis		30 1322.2	02 IN	134 30 33.370 W	
17315		Last LNM 03/97 NAD 83 bast - Gastineau Channel to Taku Inlet		(CCGD17)			20/97
	Add :	rock, 3 fathoms		58°18'34.4	83"N	134°41"20.857"W	
		rock, awash		58°18'22.6		134°40"55.912"W	
		shoal, 9 fathoms		58°19'03.5		134°41"26.147"W	
		rock 1 ¾ fathoms rock 4 fathoms		58°18'28.9 58°16'52.7		134°41.22.621W 134°45"27.897"W	
		rock 2 fathoms		58°16'43.4		134°44"18.427"W	
		rock 3 1/4 fathoms		58°17'19.5		134°41"00.080"W	
		rock 5 1/4 fathoms		58°15'52.8		134°42"54.807"W	
		rock 3 ¼ fathoms		58°17'07.3		134°40"50.229"W	
		shoal covers 1 fathom rock awash ½ fathom		58°14'18.2 58°15'38.2		134°43"23.658"W 134°42"22.196"W	
		rock covers 2 fathoms		58°12'09.1		134°38"40.737"W	
		shoal covers 2 ¼ fathoms		58°15'08.8		134°41"55.630"W	
		shoal covers 61/2 fathoms		58°15'22.2	OO"NI	134°38"53.370"W	

17316	16th Ed. 01/05/91	Last LNM 09/97 NAD 83	(CCGD17)		20/97
	AK - Southeast Co	past - Lynn Canal - Icy Strait to Point Sherman			
	Add:	rock, 3 fathoms	58°18'34.483"N	134°41"20.857"W	
		rock, awash	58°18'22.622"N	134°40"55.912"W	
		shoal, 9 fathoms	58°19'03.568"N	134°41"26.147"W	
		rock 1 ¾ fathoms	58°18'28.963"N	134°41.22.621W	
		rock 4 fathoms	58°16'52.733"N	134°45"27.897"W	
		rock 2 fathoms	58°16'43.491N	134°44"18.427"W	
		rock 3 ¼ fathoms	58°17'19.530"N	134°41"00.080"W	
		rock 5 ¼ fathoms	58°15'52.888"N	134°42"54.807"W	
		rock 3 ¼ fathoms	58°17'07.337"N	134°40"50.229"W	
	Add (Inset):	depth, 12 fathoms	58°05'11.000"N	134°47"03.000"W	
	Delete(Inset):	depth, 16 fathoms	58°05'11.000"N	134°47"07.000"W	
17320-		Last LNM 37/96 NAD 83 Coronation Island to Lisianski Strait	(NOS-CL-1519/96)		20/97
	Add:	10 fathom, (label) Rk rep 1996 (PA),	57°40'55.000"N	134°43"25.000"W	

VII GENERAL

ALASKA- AIDS TO NAVIGATION SEASONAL COMMISSIONINGS

The following aids to navigation have been commissioned for the season:

(LLNR 25615)
(LLNR 27565)
(LLNR 27570)
(LLNR 27595)
(LLNR 27590)
(LLNR 27605)
(LLNR 27600)
(LLNR 27615)
(LLNR27610)

ALASKA- ALASKA PENINSULA WATERWAYS ANALYSIS AND MANAGEMENT SYSTEM (WAMS)

1. The Coast Guard is conducting a Waterways Analysis and Management System (WAMS) study of the Sitkinak Strait Waterway which includes Sitkalidak Strait, Geese Channel, Alitak Bay and Moser Bay. The study focuses on the area's aids to navigation system, waterborne commerce, marine casualty information port/harbor resources, capabilities, and future development projects.

2. The Coast Guard is conducting a Waterways Analysis and Management System (WAMS) study of the Alaska Peninsula Waterway which includes the Semidi Islands, Chignik Bay, Sand Point, Korovin Strait, Popof Strait and Unga Strait. The study focuses on the area's aids to navigation system, waterborne commerce, marine casualty information, port/harbor resources, capabilities, and future development projects.

Any interested company or individual wishing to provide comments or participate in these two user surveys should contact:

Commanding Officer USCGC FIREBUSH (WLB 393) P.O Box Kodiak, AK 996190653 Attn: WAMS Officer (907) 487-5303

IX <u>ADDITIONAL ENCLOSURES</u>

U. S. Coast Pilot 9 Change No. 11
U. S. Coast Pilot 9 Change No. 12
U. S. Coast Pilot 9 Change No. 13
News Release CCGD17 88-97

K. A. Hamblett
Commander, U.S. Coast Guard
Waterways Management and Navigation Safety
Branch
Seventeenth Coast Guard District
By direction of the Commander

Operational Excellence Through Leadership, Teamwork And Continuous Improvement